

AUGUST 2018

REPAIRS

# LOAD PINS REPLACEMENT

## TANDEM LIFT ZPMC STS CRANE



### THE CHALLENGE


Ensuring the safe working conditions of the crane. A good, working overload protection is a must. All load pins of the Tandem Lift STS Cranes needed to be replaced to apply to the latest regulations.

### THE SOLUTION

STARKON supplied the specialized tools, method statement, and workforce to perform the job.

### THE RESULT

All eight load pins on each of the cranes were replaced and successfully tested.



<https://starkon.nl/project/load-pins-replacement>

### STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | [info@starkon.nl](mailto:info@starkon.nl) | [www.starkon.nl](http://www.starkon.nl)