

JANUARI 2019

REPAIRS

# STS CRANE LASHING PLATFORM

LASHING PLATFORM



## THE CHALLENGE

After a collision between a container vessel and a container crane, the lashing platform of the crane was damaged in such a way that the crane is no longer operational.

## THE SOLUTION

STARKON started the incident repair procedure and started with the repair within one week after the order. We removed the platform and transported it with the help of SPMT machines, to the repair site. The first step was to remove the platform and modify the crane in such a way that it was operational again.

## THE RESULT

After two weeks, the crane was operational again. The repair of the lashing platform is currently ongoing, and completion is expected at the beginning of March.



<https://starkon.nl/project/sts-crane-lashingplatform>

## STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | [info@starkon.nl](mailto:info@starkon.nl) | [www.starkon.nl](http://www.starkon.nl)