

OCTOBER 2018

REPAIRS

STS CRANE TROLLEY RAIL WELD REPAIR

TROLLEY RAIL WELD REPAIR

THE CHALLENGE

More often these days, we experience issues with the high capacity container crane's trolley rail weld connection. Heavy bumps during transit also cause damage to other components and are unpleasant for the crane operators. In time, the original rail weld becomes lower than the rail itself.

THE SOLUTION

STARKON developed an economical, safe and proven repair procedure to repair the rail in a fast and safe way.

THE RESULT

A smooth transit of the rail joints in a fast, reliable and safe way.



<https://starkon.nl/project/sts-crane-trolley-rail-weld-repair>

STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | info@starkon.nl | www.starkon.nl