

2018

MAINTENANCE

# CROSS BEAM REPAIR

## CROSSBEAM CRACK REPAIR OF ZPMC STS CRANE BOOM

### THE CHALLENGE


Three ship-to-shore cranes needed an urgent repair of the booms crossbeams as cracks appeared in the main structure.

### THE SOLUTION

Rather than do a quick repair, STARKON developed a method statement to repair the structure for longer life.

### THE RESULT

Three cranes were repaired by replacing and modifying the boom crossbeams structure by our STARKON crane team. Each crane was completed in one week.



<https://starkon.nl/project/cross-beam-repair>

### STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | [info@starkon.nl](mailto:info@starkon.nl) | [www.starkon.nl](http://www.starkon.nl)