

2020

REPAIRS

ACCIDENT RECOVERY REPAIRS

INSTALLATION AND MODIFICATION TO THE WORLD'S FIRST HEAVE COMPENSATED

THE CHALLENGE


After an incident with a straddle carrier, the client needed the damage repaired as soon as possible so the machine can be operational again.

THE SOLUTION

On a Friday afternoon, the client requested STARKON to repair the damage to the straddle carrier. As there were no spare parts available in such short notice, together we decided to repair the damaged parts in our workshop.

THE RESULT

STARKON repaired the damage in 3 days. The client was happy with the fast intervention and now have an operational and available machine again.



<https://starkon.nl/project/accident-recovery-repairs>

STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | info@starkon.nl | www.starkon.nl