



TROLLEY WHEEL REFURBISHMENT

NELCON STS CRANE

THE CHALLENGE

STARKON's client requested an overhaul of a set of trolley wheels on a Nelcon STS crane.

The STARKON team was involved in the new build of the crane 20 years ago. The project was a fun one to accept.

THE SOLUTION

In STARKON's workshop the wheels, as well as the bogies, were overhauled and modified. This should ensure many more years of use.

THE RESULT

A set of new high-quality wheels and bogies on the crane which will take it into another decennium at least.



<https://starkon.nl/project/trolley-wheel-refurbishment/>

STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | info@starkon.nl | www.starkon.nl