

2021

MODIFICATIONS

GONDOLA SUPPORT FRAME INSTALLATION AND MODIFICATION

ON TWO STS CRANES

THE CHALLENGE


STARKON's client requested the installation and modification of his Gondola Support Frame by removing and replacing several constructal welded parts for operational purpose.

THE SOLUTION

STARKON set up the Method Statement and planning. This was discussed and approved by the customer, and STARKON started the job, prepared parts, and organized tools etc.

THE RESULT

STARKON prepared the additional parts in their own workshop and managed to execute the works onsite according to plan. Of course, this was followed by some conservation work afterwards.



<https://starkon.nl/project/gondola-support-frame-installation-and-modification>

STARKON BV

Nijverheidsweg 22 | 3251 LP Stellendam | The Netherlands | +31 (0)187 665 122 | info@starkon.nl | www.starkon.nl